

Method for producing coatings based on SiC/MAX composites involves preparing a mixture of MAX-phase component powders, applying it to the surface of the workpiece, igniting the mixture with concentrated solar radiation, and performing alloying by self-propagating high-temperature synthesis. SiC powders are added to the main mass of MAX-phase powders.