

Method for splitting rolled stock involves applying a stress concentrator to the rolled stock in the splitting plane by shifting the workpiece radially relative to the axis of the rolled stock in a single working stroke, using the unloading energy of the press. The final separation of the billet is performed using the segment-by-segment shift method in a direction opposite to that in which the stress concentrator was applied.