

Method for manufacturing profiles from austenitic steels involves heating solid billets, applying a process lubricant to the surface, pressing into a die, and subsequently cooling in water. The heating temperature prior to pressing is determined based on the temperature of metal maximum plasticity, the diameter of the press chamber, and the diameter of the die.