

Calibrator has body with wear-proof inserts that go out of overall dimensions of the body and form working surface. To increase effectiveness of calibration of shaft of well in process of its drilling due to permanent contact of wear-proof inserts with wall of well, part of perimeter of the body is arranged with radius equal to radius of drill bit, and wear-proof inserts are placed at that part of the body.