

Method for controlling heat fire detectors with a thermoresistive sensing element involves applying a heat stimulus to the sensing element of the heat fire detector and measuring the parameters of its output signal. An electric current, described by the Heaviside step function with a predetermined value, is passed through the thermoresistive sensing element of the heat fire detector, and the rate of change of the heat fire detector's output signal is measured at two predetermined time points.