

Method for removing graphite stack from nuclear facilities involves the use of a rotating platform equipped with a hydraulic lifting system. A robotic remote manipulator equipped with suction cups and thermal cutting equipment is attached to the rotating platform; it cuts the graphite blocks and, together with the hydraulic lifting system, unloads them and transports them to a radioactive waste storage container.